

Product Bulletin




TrueStart™ Ignition Products

Hot Surface Igniters

TrueStart™ hot surface igniters feature protective, dynamic, and informative packaging. TrueStart™ hot surface igniters are 100% tested and completely reliable. They are compatible with all OEM furnaces.

TrueStart™ hot surface igniters are available as direct replacement for OEM (silicon carbide) or as a universal igniter (silicone carbide or silicon nitride).


Universal hot surface igniters allow a contractor to reduce truck stock and replace hundreds of OEM igniters with just one SKU.



Catalog No.	Description	UOM	Order Multiple	List Price
IGN-001	TrueStart Hot Surface Igniter, Universal, Silicon Carbide	EA	6	\$54.00
IGN-1F	TrueStart Hot Surface Igniter, Universal, Flat, Silicon Nitride	EA	6	\$88.00
IGN-1R	TrueStart Hot Surface Igniter, Universal, Round, Silicon Nitride	EA	6	\$76.00
IGN-2	Wolverine Hot Surface Igniter by TrueStart, Universal, Silicon Nitride	EA	6	\$82.00
IGN-401	TrueStart Hot Surface Igniter, Direct Replacement, Silicon Carbide	EA	6	\$54.00
IGN-402	TrueStart Hot Surface Igniter, Direct Replacement, Silicon Carbide	EA	6	\$54.00
IGN-403	TrueStart Hot Surface Igniter, Direct Replacement, Silicon Carbide	EA	6	\$54.00
IGN-409	TrueStart Hot Surface Igniter, Direct Replacement, Silicon Carbide	EA	6	\$54.00

Pilot Burners


TrueStart™ pilot burners are a direct replacement for Carrier/BDP pilot burners. Available in 2-wire and 3-wire versions. The 3-wire is also field convertible to a 2-wire. TrueStart™ pilot burners are not manufactured by Carrier Corporation.



Catalog No.	Description	UOM	Order Multiple	List Price
FC-73	2 Wire Pilot Burner – Replacement for the Carrier®/BDP 732 2 wire pilot burner commonly known as Carrier®/BDP part number LH33JZ053	EA	1	\$151.60
FC-74	3 Wire Pilot Burner – Replacement for the Carrier®/BDP 740A 2 wire pilot burner commonly known as Carrier®/BDP part number LH680005	EA	1	\$153.60

Blower on Relay

TrueStart™ blower on relays are direct replacements for Carrier/BDP blower on relays. TrueStart™ blower on relays are not manufactured by Carrier Corporation.



Catalog No.	Description	UOM	Order Multiple	List Price
FC-82	Blower on Relay – Replacement for the Carrier®/BDP 821 Blower on Relay commonly known as Carrier®/BDP part number HN680001	EA	1	\$214.00
FC-87	Spark Electrode – Replacement for the Carrier®/BDP 871 Spark Electrode commonly known as Carrier®/BDP part number LH680512	EA	1	\$51.20

Flame Sensor

TrueStart™ flame sensors are a direct replacement for Carrier/BDP flame sensors, cross reference part numbers are detailed in the item descriptions. TrueStart™ flame sensors are not manufactured by Carrier Corporation.



Catalog No.	Description	UOM	Order Multiple	List Price
900-3	TrueStart™ FLAME SENSOR replaces Carrier® LH33WZ516	EA	1	\$24.00
900-4	TrueStart™ FLAME SENSOR replaces Carrier® LH33WZ517	EA	1	\$26.00
900-5	TrueStart™ FLAME SENSOR replaces Carrier® LH33WZ518	EA	1	\$24.00
900-6	TrueStart™ FLAME SENSOR replaces Carrier® LH33WZ520	EA	1	\$24.00